

GRAFIKU I PUNIMEVE

Objekti: Rehabilitimi i Kanalit Ujites U.3-24 ; U-325/1; U-3/25/2 ne Fshatin Krutje e Poshtme Njesia Administrative Krutje, Bashkia Lushnje

Nr	Analiza	Emertimi I Punimeve	Muaji I	Muaji II	Muaji III	Muaji IV
1	3.96/b	Germim dheu me eskavator zinxhir 0.25 m3, ne kanale gjeresi > 2m, prani uji 1m, kategoria III, me shk ne toke				
2	3.161/2	Rrafshim skarpate ne germim, eskavator 0.25m3				
3	3.17	Germim dheu ne seksion te lire me krah, ne toke te bute, kateg I-III, pa hedhje				
4	3.208	Shtrese cakulli t=10cm nakadan, perhapur e ngjeshur me makineri				
5	3.158/4a	Transport auto deri ne 4 km				
6	3.243	Struktura te holla monolite betoni C16/20				
7	2.181	Konstruksione metalike te perbera				

"SIRE-ALB" sh.p.k.

Administrator

Ing. Renaldo KARAJ

**Renaldo
Karaj**

Digitally signed by Renaldo
Karaj
Date: 2024.05.30 14:08:29
+02'00'

